



ORIGINAL ISSUE DATE: July 11, 2003  
Recertification due: November 2009

PROGRAM ADMINISTRATOR  
DEPARTMENT ALECP  
INTERTEK  
ETL SEMKO Division  
3933 U.S. ROUTE 11  
CORTLAND, NY 13045-0950

An Activity Sponsored and Administered by  
Intertek

AMERACE  
A DIVISION OF THOMAS & BETTS  
77 WEST BEAVER CREEK RD  
RICHMOND HILL, ONTARIO  
CANADA L4B 3A7

**AIRPORT LIGHTING  
EQUIPMENT  
CERTIFICATION PROGRAM**

**CERTIFICATE OF  
CONFORMANCE**

The product described below is hereby approved for listing in the next issue of the Advisory Circular 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program" issued by Federal Aviation Administration. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Administrator of the results of such tests, accompanied by related documents, by an Intertek recognized testing laboratory.

1. The listing below will be added to the next published Directory.

L-823 – Connectors, Cable (AC 150/5345-26C)				
Manufacturer	Type	Style	Class	Manufacturer's Catalog Number
Amerace.	II	1	A	95MPX-X
	II	1, 7	A	95MPR7X-X
	II	1, 8	A	95MPR8X-X
	II	6	A	95MP6X-X
	II	7	A	95MR7X-X; 96MPPR7X-X; 96MPR7R7X-X
	II	8	A	95MR8X-X; 95MPPR8X-X; 96MPR8R8X-X

2. This Certification requires continuing validation in accordance with the requirements of the Advisory Circular noted above and the Intertek Airport Lighting Equipment Certification Program. Confirmation of current certification may be obtained at [www.faa.gov/arp/150acs.cfm](http://www.faa.gov/arp/150acs.cfm)

3. Product tested and Report issued by: Intertek; Amerace

(A) Report No: 3005139-001A; 03-04; 03-06

(C) FAA Specification No.: AC No. 150/5345-26C

(B) Date of Report: 11/2001; 6/2003; 6/2003

(D) Date of Receipt of Report by the Administrator:  
July 2003

Approved for Certification by:

NOTE: PLEASE REVIEW, AND ADVISE ADMINISTRATOR AT INTERTEK IMMEDIATELY IF DATA, AS SHOWN, NEED TO BE CORRECTED.

David C. Edwards, Program Administrator

Date: July 11, 2003

